

- 1. Darling 4. A.P. Smith
- 2. Kennedy 5. Matthews
- 3. Mueller 6. R.D. Wood

Dallastown-Yoe Water Authority



Hydrant Record
Year: 2018

ID #	Note	Location	Type	Year Made	Feed	Pressure (psi)		Flow (gpm)	Flushed (min)	Needs Repair	Last Inspected	Comments/Notes
						Static	Residua					
YT 218)	Lombard Rd. at Sheetz	1	1997	6"						2" needs tightened	Call Sheetz before flush 246-8144 Northville Green (Weis) 1-248-547-0808 x 106
X		<i>Blow-off behind Sheetz</i>			6"						No Longer Exists	NO LONGER EXISTS
YT 217)	Jonathan Way at Lombard Rd.	1	2015	6"						"	Call Mrs. Landis prior to flushing 244-5080, 134 S Maple
YT 216	*	Intersection of Lombard Rd. & Appleton Dr.	1	2015	6"						"	FLUSH TOWARD STREET NOT YARD
YT BO1)	<i>Blow-off behind Apple Ford</i>			6"						"	
YT 222		131 Jonathan Way N	3	1988	6"					X	"	Leaks @ stand pipe
YT 220	*	187 Jonathan Way N.	3	1988	6"						"	Close valve #1 designated on map A below, and leave closed until instructed to re-open
YT 221		Intersection of Jonathan Way N. & Love Ave.	3	1988	6"						"	↓
YT 224		Love Ave. at Chapel Church Rd.	3	1988	6"						"	↓
YT 225		Chapel Church Rd.	1	1989	6"						"	↓
YT BO2		<i>Blow-off at the intersection of Chapel Church Rd. & Cape Horn Rd.</i>			6"						"	↓
YT BO3		<i>Blow-off on Chapel Church Rd.</i>			6"						"	↓
YT 223		21 Steeple Ave.	3	1988	6"						"	DRAINS SLOW
YT 219		203 Jonathan Way N.	3	1988	6"						"	↓
YT BO4	*	<i>Blow-off in Chapel Way cul-de-sac</i>			6"						"	map A --re-open valve#1, close #2, then flush blow-off. Leave valve #2 closed.
YT 215		1002 Apple Valley Dr.	1	1988	6"						"	↓
YB2		E. High St. at N. Main St.	3	2010	4"						"	↓

1. Darling 4. A.P. Smith
2. Kennedy 5. Matthews
3. Mueller 6. R.D. Wood

Dallastown-Yoe Water Authority



Hydrant Record
Year: 2018

ID #	Note	Location	Type	Year Made	Feed	Pressure (psi)		Flow (gpm)	Flushed (min)	Needs Repair	Last Inspected	Comments/Notes
						Static	Residual					
YB4		Intersection of E. George St. & N. Main St.	3	2006	6"							↓
YB3		61 W. George St.	1	1985	6"					✗		Leaks around bonnet
YB BO1		Blow-off W. George & N. Maple			6"							↓
YB BO2	*	2" Galvanized Blow-off on W. George St. Ext.			2"							Blow-off is located in second curb box. Water comes from same curb box.
YB1		Intersection of N. Maple & W. High St.	1	1991	6"							CALL James Geubtner, 246-1964
YT BO5		Blow-off at creek on Yoe Dr.			8"							↓
YT BO6		Blow-off on Yoe Dr.			8"					✗		NEEDS 2" TRIM RING
YT 212		360 Yoe Dr.	1	2005	6"							↓
YT 214		520 Katonah Dr.	1	2003	8"							↓
YB BO7	LP	Blow-off at end of Katonah Dr.			8"							UNABLE TO LOCATE
YT 213	*	115 Heather Glen Dr.	1	2002	8"							Open valve #2 prior to flushing.
YB BO8		Blow-off on Heather Glen Dr.			8"							UNABLE TO LOCATE
YT 194		Intersection of Glen Ave. & E. Main St.	1	2015	8"							Draws slow
YT 226		Behind Dairyland Square	2	1974	6"							Drains slow 244-7077
YT BO9		Blow-off in Glen Ave. cul-de-sac			6"							
YT 193		600 block of Green Meadows Drive	3	1981	6"							
YT BO10	*	Blow-off in Green Meadows cul-de-sac			6"							Blow-off is located in grass at the edge of the far end of the cul-de-sac/will flood front doors

1. Darling 4. A.P. Smith
2. Kennedy 5. Matthews
3. Mueller 6. R.D. Wood

Dallastown-Yoe Water Authority



Hydrant Record
Year: 2018

ID #	Note	Location	Type	Year Made	Feed	Pressure (psi)		Flow (gpm)	Flushed (min)	Needs Repair	Last Inspected	Comments/Notes
						Static	Residual					
YT 192		500 block of Green Meadows Drive	3	1980	6"							CALL SUE BOONE @ VICTORIA VILLAS, 495-5695
YT 196		Intersection of Holly Hill Dr. & Glen Terrace	5	1951	6"							
YT 195		at King's Point townhouses	1	1985	6"							
YT BO11		<i>Blow-off at King's Point townhouses</i>			6"							
D101		at Trolley Dr. apartments	2	1974	6"							Put wrench on the next blow-off prior to flushing
YT B012		<i>Blow-off at Trolley Dr. apartments (#1)</i>			6"							Place a 2" & 1 1/2" riser to bring up to grade
YT BO13		<i>Blow-off at Trolley Dr. apartments (#2)</i>			6"							
D137		S. Park St. at tanks	1		8"					×		Leaks around bonnet
D136		Intersection of S. Park St. & E. Market Ave.	1	1914	8"					×		leaks around bonnet
D104		Intersection of E. Main St. & S. Park St.	1	1978	6"							
D103		Intersection of E. Main St. & S. Duke St.	1	1914	6"							
D102)	Intersection of E. Main St. & S. High St.	1	1992	6"							Call Gichner's prior to flushing. Phone: 244.7611
D134		50 Frederick St.	1	1914	6"					×		LEAKS BAD AROUND BONNET * MISSING BOLT-GASKET MISSING ON STEAMER CAP
D135		525 E. Frederick St.	1	1998	6"					×		Missing top bolt **
D BO1		<i>Blow-off in Frederick St cul-de-sac</i>			6"							
D BO2)	<i>Blow-off on S. Duke St.</i>			6"							
D BO3	*	<i>Blow-off on E. Park Ln.</i>			6"							Blow-off is located behind senior home on E. Main St.