

Dallastown-Yoe Water Authority

ID #	Note	Location	Type	Year Made	Feed	Pressure (psi)		Flow (gpm)	Flushed (min)	Needs Repair	Last Inspected	Comments/Notes
						Static	Residual					
YT 161		123 Teila Dr.	1	1975	6"							
YT 159		Ridgeford Rd. at Teila Dr.	1	1975	6"							
YT 160		239 Teila Dr.	1	1975	6"					X		Missing 1 top bolt
YT 172		529 Gary Dr.	2	1974	6"							Use diffuser on back of truck washes out driveway
YT 148	*	S. Franklin St. at Dallas Dr.	1	1989	8"							Place cones to slow traffic.
YT 149	*	Franklin Square Dr. at S. Franklin St.	1	1989	6"					X		LEAKS BADLY @ BONNET Call John Slackey(carwash) 757-4719
YT 150		135 Franklin Square Dr.	1	1989	6"							
YT 151		Franklin Square Dr. at Perring Dr.	1	1989	6"							
YT 152		285 Franklin Square Dr.	1	1989	6"							
YT 153		325 Franklin Square Dr.	1	1989	6"							Leaks around turn on valve at top real bad when opened
YT 154		Pulaski Place entrance	1	1989	6"							Floods Driveway
YT 155	*	444 Pulaski Place ₁	1	2004	6"							Close valve #1 designated on map C below, then flush. Leave valve closed.
YT 156		472 Pulaski Place	1	2004	6"							↓
YT 155	*	444 Pulaski Place ₂	1	2004	6"							Re-open valve #1, close valve #2, then flush for 2 nd time. Re-open valve #2.
YT 157		435 Ridgeford Rd.	1	1975	6"							
YT 158		Leaderton Drive	1	1975	6"							212 Leaderton Dr, very hard to turn
YT BO30		BO Honey Valley & Franklin			6"							
YT 126	9	2952 Honey Valley Rd.	2	1975	8"							Call R.A. Martin prior to flushing. Phone 741-1124(CAN'T HARDLY TURN)
YT 125		2904 Honey Valley Rd.	2	1974	8"							CALL Sandra Warren Sweitzer 246-3090 SEE MAP C, HARD TO TURN

Dallastown-Yoe Water Authority

ID #	Note	Location	Type	Year Made	Feed	Pressure (psi)		Flow (gpm)	Flushed (min)	Needs Repair	Last Inspected	Comments/Notes
						Static	Residual					
YT 145	*	325 Majestic Circle	1	2000	6"							Close valve #4 designated on map B below prior to flushing. Valve #4 needs thicker cap.
YT 146		357 Majestic Circle	1	2000	8"							↓
YT 147	*	377 Majestic Circle (x2)	1	2000	8"							Close valve #1, then flush. Re-open valve #1, close valve #2, and flush again. Re-open valves #2 and #4
YT 127		Exeter Dr. N. cul-de-sac	1	2000	6"							
YT 128		2921 Exeter Dr. S.	1	1977	6"							
YT 129		2969 Exeter Dr. S.	1	1978	6"							
YT 131		2928 Woodshead Terrace	1	1978	6"							
YT 130		2960 Woodshead Terrace	3	1983	6"							
YT BO31	*	Blow-off at end of Woodshead Terrace			6"							Rake back mulch.
YT 132		625 Spartan Rd.	1	1978	6"							
YT 134	*	2920 Starfire Dr.	1	1979	6"							Check thread pattern (2 1/2). NST pattern lead in
YT BO32		Blow-off in Starfire Dr. cul-de-sac			6"							
YT 133	*	589 Spartan Rd.	1	1979	6"							Check thread pattern.(2 1/2) CAUTION FLOODS HOUSE NST pattern lead in
YT BO33		Blow-off at 569 Spartan Rd.			6"							
YT 135		Fiesta Dr. at Flora Ln. (east end)	1	1979	6"							NST pattern
YT 137		Fiesta Dr. at Flora Ln. (west end)	1	1982	6"							Hydrant hit by vehicle, called B. Miller Yk Twp 5/14/14 NST pattern
YT 136		2850 Fiesta Dr.	1	1980	6"							NST pattern
YT 121	*	701 St. John's Pl. at Honey Valley Rd.	3	1979	6"							Opposite hydrant Close valve slowly. Ball slams shut.
YT 122	*	727 St. John's Pl.	3	1979	6"							Opposite hydrant