

- 1. Darling 4. A.P. Smith
- 2. Kennedy 5. Matthews
- 3. Mueller 6. R.D. Wood

Dallastown-Yoe Water Authority



Hydrant Record
Year: 2018

ID #	Note	Location	Type	Year Made	Feed	Pressure (psi)		Flow		Flushed (min)	Needs Repair	Last Inspected	Comments/Notes
						Static	Residual	(gpm)	(min)				
D141	*	at E. Maple St. apartments	1		6"						✗	"	Hydrant is located in front of 506-528 E. Maple St. Leaks @ bonnet & 2" side connector-Left
D142		Intersection of E. Maple St. & N. Glen Ave.	1	1914	6"						✗	"	Leaks @ bonnet, entire bonnet moves when opening & closing hydrant Missing gasket on steamer
D146		44 E. Maple St.	1	2011	4"							"	NS sides
D145		114 E. Maple St.	1	2011	4"							"	NS sides
D144		BUMS parking lot	1	2011								"	NS sides
D143		E. Maple St. at John H. Myers	1		4"							"	Does not thread correctly NOT ENOUGH FOR READING
D105)	E. Main St. at St. Joseph's	1	2000	8"						✗	"	Steimer cap is stuck/-still cannot get off-used Left side connector
D106		Intersection of E. Main St. & N. Pleasant Ave.	2	1999	8"							"	
D107		Intersection of E. Main St. & N. Charles St.	1	2000	8"							"	
D108		Intersection of E. Main St. & Franklin Alley (at 55 E. Main St.)	1	2000	8"							"	
D109		Intersection of E. Main St. & N. Walnut St.	1	1997	8"							"	
D133		101 S. Pleasant Ave.	1	2000	8"							"	
D131		Intersection of S. Pleasant Ave. & E. Queen St.	1	2000	8"							"	
D129		Intersection of S. Pleasant Ave. & E. Girard Ave.	1	2000	8"							"	
D127		Intersection of S. Pleasant Ave. & Boundary Ave.	1	2000	8"							"	
D132		149 S. Charles St.	3	2016	6"							"	Does not register residual or GPM or guage
D130		223 S. Charles St.	1	2004	6"							"	does not register residual or GPM or guage
D128		337 S. Charles St.	3	2016	6"							"	
D BO4	*	<i>Blow-off on E. Girard Ave.</i>			6"							"	and close valve on Girard. 4. Flush. 5. Re-open Girard valve.
D123		Intersection of E. Howard St. & Devers St.	1	2013	6"							"	
D121		W. Cherry Ln. behind Turkey Hill	1		6"							"	

- 1. Darling 4. A.P. Smith
- 2. Kennedy 5. Matthews
- 3. Mueller 6. R.D. Wood

Dallastown-Yoe Water Authority



Hydrant Record
Year: 2018

ID #	Note	Location	Type	Year Made	Feed	Pressure (psi)		Flow (gpm)	Flushed (min)	Needs Repair	Last Inspected	Comments/Notes
						Static	Residual					
D121		W. Cherry Ln. Behind Turkey Inn	1		0"							
D122		Intersection of S. Walnut St. & E. Howard St.	1	1914	4"							Call Mrs. Dehoff - 717-244-2457
D120		S. School Pl. at fire house	2	1981	6"							
D124		Intersection of S. Walnut St. & W. Queen St.	1	2011	6"							
D125		Intersection of S. Walnut St. & E. Gay St.	1	2011	6"							
D126		Intersection of S Walnut & W Broundary	1	2009	6"							1 2/1 are National standard thread
D110		41 W. Main St.	1	1997	8"							Call Mrs. Dehoff before you flush, she lives @ 64 S. Franklin St., 244-2457
D111		101 W. Main St.	1	2015	8"							
D112		N. School Pl. at St. Paul's	1	1957	6"							
D118		Intersection of S. Franklin St. & W. Cherry Ln.	1	1957	4"							Does not read
D119		53 S. Franklin St.	1	1986	4"							use diffuser or 58 will flood
D117		Intersection of W. Cherry Ln. & Daugherty Ln.	1	1983	6"							
D BO5		Blow-off on W. Cherry Ln.			6"							Valve box need dug-up & re-aligned
D113		337 W. Main St. at N. Mason Alley	1	2000	8"							

1. Darling 4. A.P. Smith
2. Kennedy 5. Matthews
3. Mueller 6. R.D. Wood

Dallastown-Yoe Water Authority



Hydrant Record
Year: 2018

ID #	Note	Location	Type	Year Made	Feed	Pressure (psi)		Flow (gpm)	Flushed (min)	Needs Repair	Last Inspected	Comments/Notes
						Static	Residual					
D114		379 W. Main St. at Conway Alley	1	2014	8"							
D115		418 W. Main St. at Daugherty Alley	1	2000	8"							
D116		454 W. Main St. at Stine Alley	1	1991	8"							
D BO6		<i>Blow-off at 56 Willow Ave.</i>			6"							CALL: Carol Robbins 244-8033, 880-7743
D147		Hydrant @ Maple St garage	3	2011	6"							
D148		100 W. Maple St. at Lawson Alley	3	2011	6"							
D149		298 W. Maple St. at N. Star Alley	1	2006	4"							DOES NOT DRAIN
D153		W. Chestnut & Carter, 1st time	1	2006	6"							Complex beside Tanglewood, across from retention pond
D152)	N. Cedar St. at W. Chestnut St.	1		6"							Turns very hard both open & close. Call Christine Williams one day prior to flushing.
D150		Intersection of W. Maple St. & N. Cedar St.	1		4"							368 W. Chestnut 781-3776
D154		335 W. Broad St at N. Poplar St.	1		4"					X		Stem in mydrant broke, we turned hydrant off @ hydrant valve Needs new gasket for steamer cap
D155		Intersection of W. Broad St. & N. School Place	1		4"							Doesn't drain right
D151	*	W. Broad St. before cul-de-sac	1	2001	6"							Close valve on Blossom Hill, then flush. Re-open Blossom Hill valve, and close valve on N. Cedar. Flush, then re-open.
D156		W. Chestnut St. at dead end	1		6"							
D157		N. School Pl. at Tanglewood	1	1978	6"							
YT 201	*	440 Tanglewood Dr.	1	1981	6"					X		Place wrench on blow-off prior to flushing. Missing top bolt:hard to turn
YT BO14		<i>Blow Off in Tanglewood</i>			6"							
YT BO15		<i>393 Carter</i>			6"							
YT BO16		<i>Blow Off @ end of clay Ave.</i>			6"							Left corner of dead end in grass, valve @ Clay & Carter
YT BO17		<i>Blow Off @ end of Carter</i>			6"							NOW OPEN
D153	*	W. Chestnut & Carter, 2nd time	1	2006	6"							Should be Here, not at 1st time
D158	*	Intersection of	2	1973	6"					X		The backside of Colonial Dr. -VERY hard to turn, LEAKS @ bonnett